



# Sanitary Sewer Overflow Annual Report

## Division of Surface Water

<b>Date:</b> 03/31/2022		
<b>Facility Name:</b> Willoughby Eastlake STP		
<b>Ohio NPDES Permit Number:</b> 3PD00024*TD		
<b>Period Covered by Report:</b> 01/01/2021 - 12/31/2021		
<b>Contact Person:</b> John (Jack) Gorka		<b>Title:</b> Superintendent
<b>Mailing Address:</b> 221 Erie Road		
<b>City:</b> Willoughby	<b>State:</b> OH	<b>Zip Code:</b> 44095
<b>Country:</b> USA		
<b>Sanitary Sewer Overflows Spreadsheet(attachment) :</b> <i>SSO Annual SSO Form for 2021.xlsm</i>		
<b>Water In Basement Occurrences Spreadsheet(attachment) :</b> <i>SSO Annual WIB form for 2021.xlsm</i>		
<b>Narrative analysis of WIB patterns by location, frequency and cause:</b> <i>Ridge Acres Willoughby: Sanitary main was blocked by tree roots and backed up sewage into a duplex. Line was cleared.</i>		
<i>Quentin Storm Sewer Outfall Eastlake: City received a call about residents backing up. The City arrived and removed manhole lids. Manholes were surged. Attempted to unblock and noticed gravel and signs of a broken pipe. Called Traxx Excavation Company to fix broken pipe. Faculty tap connection found bags of concrete around the tap site that collapsed the main also.</i>		
<b>ADDITIONAL INFORMATION</b>		
<i>Please add any additional comments or attachments below.</i>		
<b>Certification</b>		
<i>I certify under penalty of law that I have personally examined and am familiar with the information in this report and all attachments. Based on my inquiry of those persons immediately responsible for obtaining the information contained in the report, I believe that the information is true, accurate, and complete.</i>		
<b>Name:</b> John Gorka		<b>Title:</b>
<b>Signature(Electronically submitted by):</b> John Gorka (User ID: jgorka )		<b>Submission Date:</b> 03/31/2022